

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

## **MEMORANDUM**

DATE:	- ·	
SUBJECT:		
	Facility Name:Village of Loudonville-Maintenance Department EPA ID #:OHD 987 020 724	
		<u></u>
FROM:	Erin ( ) and Sandalla	
	Erin K. Jones, Environmental Protection Specialist	
TO:	George Hamper, Chief, Corrective Action Section 2	
recommen	d the following determination regarding the need for an investigation:	
	O Determination of Need for an Investigation-Investigation is not Necessary	
	on for Determination	
	eliminary Assessment/Visual Site Inspection (PA/VSI) did not recommend any further	investigation
	A/VSI recommendations do not warrant RRB attention	
	hase 1 Environmental Site Assessment (ESA) did not recommend further investigation	e e
	nase 2 ESA did not recommend further investigation	
	nase 1/Phase 2 ESA recommendations do not warrant RRB attention	
	ompany representative asserts that the site is clean	
	ot subject to corrective action	
	nrolled in other clean-up program	
	A/VSI recommendations have been implemented	
	emoval	
	nrolled Voluntary Remediation Program	
	ompleted Voluntary Remediation Program	16
	aperfund	
	aperfund No Further Action Decision	
	uperfund Base Relocation and Closure	la .
	therE Determination of Need for an Investigation – Investigation is Necessary	
	ton for Determination	
	A/VSI recommends further investigation	
=	SA recommends further investigation	
	ther	4
	mination can be made – More Information Needed	
110 400	minution can be made Profe information receded	
ø	Moproved (A) ☐Not Approved	
	~ C; ~ \( \lambda \) \( \lambda \)	ż
Sign	ed: to grange Date: SEP 3 0 200	

**Determination Date: August 26, 2009** 

-Ingredients:

-Solvents for cleaning products: No

Determination: Company representative asserts that the site is clean Facility Contact Form (No PA/VSI)

	Facility Name:Village of Loudonville-Maintenance Department
	EPA ID#:_ OHD 987 020 724 Address: _ East Wally Road
	City: Loudonville State: OH_
	Units Closed:X01 Date: October 11, 1995
	Facility Representative: Roy Wilson Phone# 419-994-4630
	Email Address:
	Date of phone conversation: August 26, 2009
	This was never a facility so to speak. It was an area where the village put large yard waste and storm damage to burn. The contamination occurred as a result of the accelerant that was used to start the fire.
	Roy was part of the clean up operation and mentioned that in 1994-1995 when the Ohio EPA came out to evaluate closure activities the inspector asked why they had dug up so much of the site. Roy said that the boss who had instructed the burn with the hazardous accelerant had them dig 2 or 3 times as much of the ground up, both deeper and wider, to ensure that the contaminated area was cleaned beyond standard. The closure was a clean and haul operation.
	Y / Is there known soil or groundwater contamination? Contaminants:
	Y / Has the parcel been split or was there a change in ownership?
	Y / Was a Phase 1 or Phase 2 report prepared in connection with a sale of the property?  Y / Can we have a copy?  N Is the facility currently operating?
	This is currently a parking lot adjacent to a community park. The parking lot is not paved with asphalt but is a loose compacted stone.
V	When was the plant built?  N/A
	What products are/were made?  N/A
V	What chemicals were used in the process?